

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	((drill\$3 adj bit) and wear \$3 and hard\$4 and control \$4 and ream\$3 and gauge and protect \$4).clm.	US- PGPUB; USPAT	OR	ON	2008/10/14 09:08
L2	0	((drill\$3 adj bit) and (wear \$3 (wear adj resist \$4)) and hard\$4 and control \$4 and ream\$3 and gauge and protect \$4).clm.	US- PGPUB; USPAT	OR	ON	2008/10/14 09:09
L3	0	((drill\$3 adj bit) and (wear \$3 (wear- resist\$4)) and hard \$4 and control\$4 and ream \$3 and gauge and protect\$4). clm.	US- PGPUB; USPAT	OR	ON	2008/10/14 09:09

10/14/08 9:09:34 AM

C:\ Documents and Settings\tbomar\ My Documents\ EAST\ workspaces  
\ 10580710.wsp